


# Photographs of Barrel TPG/BeO/Epoxy Baseboard




#183.184.185

Epoxy burrs

Epoxy around edge (~0.3mm)



Thermal distortion?

Thermal breaking?



#185-Cooling side  
BeO cracking is seen

#183 Epoxy burrs  
partially fitting the slot



SCT20000530KEK