






Thickness of Baseboard

Summary of 1976 Baseboards up to last week.



Thickness of Epoxy

Summary of 1976 Baseboards up to last week.



⇒ Approximately $27\mu\text{m}$ of epoxy on each side in average.