

From M.D.Gibson@rl.ac.uk Thu Jan 18 19:48:36 2001
Date: Wed, 17 Jan 2001 16:25:08 -0000
From: "Gibson, MD (Martin) " <M.D.Gibson@rl.ac.uk>
To: 'Nobu Unno' <unno@post.kek.jp>
Cc: "Apsimon, RJ (Richard) " <R.J.Apsimon@rl.ac.uk>,
"A. A. Carter (E-mail)" <a.a.Carter@qmw.ac.uk>
Subject: updated drawings

[The following text is in the "iso-8859-1" character set]
[Your display is set for the "ISO-2022-JP" character set]
[Some characters may be displayed incorrectly]

Hi Folks,
There is now another set of drawings on the FTP site as before.

eng.rl.ac.uk
anonymous
pub
pford.

The only changes concern the metalized bonding pads.

Things you need to know....

On the top far side facing we have removed the vertical arm from the semicircular annulus, because it was causing cracks in the facing at the time of baseboard fabrication.

On the top cooled facing we have modified the pad to be a complete annulus with no vertical features for the same reason as on the small facing.

I think that you will find that there is still ample room for wire bonds.

We are trying to reduce the thickness of the metalisation to further cure this problem.

cheers

Martin

M.D.Gibson@rl.ac.uk
phone 44 (0) 1235 44 5258
Fax 44 (0) 1235 44 6733